



Professional Strength

High Foaming

Concentrated Acid Cleaner



Meets Standards For Use
In USDA Facilities

Cleans & Brightens Aluminum Surfaces



Net Contents: On Containers

Caution:
For Professional Use Only.
Keep Out Of Reach Of Children.
Please read all precautions and SDS
before using this or any product.

A high-foaming concentrated acid cleaner, formulated for removal of mineral deposits, such as milkstone, beerstone, light rust and scale from outside surfaces of all food processing equipment. Brightens steel and aluminum.

DIRECTIONS

Dilute 2-4 oz. of product per gallon of water. May be used with foaming or pressure washing equipment, as well as for manual applications.



Danger!
Causes severe skin burns and eye damage.
Causes serious eye damage.

Prevention:

Do not eat, drink, or smoke while using this product.

Avoid breathing fumes, mist and overspray as much as possible. Use only in well ventilated areas.

Eyes: Wear safety glasses when handling product. **Skin:** Wear appropriate gloves to prevent skin exposure.

Clothing: Wear appropriate protective clothing to prevent skin exposure.

Respirators: Follow the OSHA respirator regulations if exposure limits are exceeded or if irritation or other symptoms are experienced.

Precautionary Statements (First Aid):

Eyes: Immediately flush eyes with plenty of water for at least 15 minutes, occasionally lifting the upper and lower eyelids. Remove contact lenses if present and easy to do. Get medical attention immediately if irritation persists.

Skin: Immediately flush skin with plenty of water for at least 15 minutes while removing any contaminated clothing and shoes. Discard contaminated clothing in a manner which limits further exposure, making sure to wash before reuse. Contact a physician immediately if irritation persists.

Ingestion: Do not induce vomiting. If victim is conscious and alert, give 2-4 cups of water. Never give anything by mouth to an unconscious person. Get medical attention immediately.

Inhalation: Remove from exposure and move to fresh air immediately and keep comfortable for breathing. If breathing is difficult, give oxygen. If breathing has ceased apply artificial respiration using oxygen and a suitable mechanical device such as a bag and a mask. Get medical attention immediately if irritation persists.

Notes to Physician: Treat symptomatically and supportively. Consult a doctor and/or the nearest Poison Control Centre for all exposures.

UN1760

Corrosive Solids, N.O.S.,
(Phosphoric Acid, Sulfuric Acid),
8, PGII



To Reorder: 770.578.4240

Algonquin Products, Inc. | P.O. Box 87005 | Dartmouth, MA 02748

www.algonquinproducts.com

24 Hour Emergency Number 800.535.5053

SDS Reference Number: 1207